

FIG. 1

09781200-064404
TOTAL 00248260




FIG. 2a




FIG. 2b

09784200-061101
TOTAL 50-00278260




FIG. 2c




FIG. 2d




FIG. 2e




FIG. 3a




FIG. 3b





FIG. 4



PERFORATED
FLIGHT

FIG. 6

SLOTTED
FLIGHT

FIG. 7

PARTIALLY TRUNCATED
FLIGHT

FIG. 8

09781200.051101




FIG. 9